



Fig. 1 - Fatada Principala



Fig. 2 – Idem





Fig. 3 – Fatada B-dul Ferdinand I



Fig. 4 - Idem





Fig. 5 – Fatada Str. Bucuresti



Fig. 6 – Fatada Str. Tribunalului – Acces secundar





Fig. 7 – Detaliu fatada Principala – Acces Principal




Fig. 8 – Idem





Fig. 9 – Detaliu Fatada B-dul Ferdinand I





Fig. 10 – Detaliu Fatada Str. Bucuresti





Fig. 11 – Detaliu rost între cladiri





Fig. 12 – Idem





Fig. 13 – Fatada Curte interioara





Fig. 14 - Idem



Fig. 15 – Idem





Fig. 16 – Idem



Fig. 17 – Idem





Fig. 18 – Detalii Structura



Fig. 19 – Idem



Fig. 20 – Vedere Culoar interior





Fig. 21 – Idem



Fig. 22 – Vedere Acces Aripa laterala Stanga





Fig. 23 – Detaliu Tamplarie Interioara



Fig. 24 – Idem





Fig. 25 – Idem



Fig. 26 - Idem



Fig. 27 – Vedere tavan





Fig. 28 – Idem



Fig. 29 – Detaliu tavan cu boltisoare





Fig. 30 – Detaliu Tavan





Fig. 31 – Detaliu compozitie tavan



Fig. 32 – Idem





Fig. 33 – Detalii compozitie Pardoseala



Fig. 34 - Idem





Fig. 35 – Degradari datorate infiltratiilor cu apa



Fig. 36 – Idem





Fig. 37 – Idem



Fig. 38 – Idem



Fig. 39 – Fisuri in zidarie





Fig. 40 – Ansamblu sarpanta



Fig. 41 – Detaliu sarpanta din lemn





Fig. 42 – Idem



Fig. 43 – Vedere parte inferioara Invelitoare